



VAPOR RECOVERY MOTOR PRECAUTIONS :

The following items are not covered under Tronitec standard warranty for rebuilt vapor recovery motors :

Deterioration or failure of motor and / or its parts due to excessive gas build up from tank top offs.

Motor failure due to foreign debris inside the motor such as metal shavings, dirt and / or thread compound.

Damage due to improper storage, handling, shipping or a drop.

Please use the following precautions when handling vapor recovery motors :

- ✓ Before shipping vapor recovery motor cores please evacuate all gasoline and vapors from the motor.
 - ✓ When packaging vac motor cores for return shipment please utilize the packaging material that the new motor replacement was sent in or equivalent.
 - ✓ Securely package your vac motor cores to reduce movement and insure wires are not susceptible to tearing, cutting or other damage while in transit.
 - ✓ Insure all filters are installed and properly in place.
 - ✓ Do not allow thread compound (pipe dope), metal shavings, dirt or debris to enter the motor.
 - ✓ Do not drop the vapor recovery motor.
 - ✓ Do not carry or handle the motor by the wiring harness. Be careful not to pull, crimp, break or tear the wiring harness.
 - ✓ Store motors in a climate controlled environment prior to installation. Prolonged exposure to non climate controlled conditions causes accelerated rust and corrosion.
 - ✓ Do not cut the wiring harness less than 3 inches from the base of the motor. This can render the core non repairable.
-

TRONITEC
1800 Sandy Plains Pkwy., Suite 120, Marietta, GA 30066
800-962-2588
www.tronitec.com