TRONITEC SERVICE DOCUMENT (TSD #28)

Note: If the CRIND system locks up or a **" BUSY STUCK**" error shows, the problem is more likely the paper detect sensor on the printer and not the printer driver board.