TRONITEC SERVICE DOCUMENT (TSD#50)
WAYNE OVATION PPU DATA CABLE (Tronitec Item Code 6908)

When encountering PPU display problems, please inspect the PPU Data Cable for water and corrosion damage. Corrosion damage at the Ovation PPU Data Cable can create PPU display problems. Contact Tronitec for replacement cables (Part# 888059-002 Item Code 6908).