

# Tronitec Service Document # 53

## Item Code 6432 Gilbarco Card Reader Replacement To replace OEM Part # M02136B001

---



When installing Card Reader Item Code 6432 on Encore 300, 500S and 700S :

- Electrostatic discharge ( ESD ) Ground is incorporated into the reader connection pins.
    - An ESD Ground Connection wire is not needed.
  - Remove the existing ESD Ground wire from dispenser chassis or insulate the connection pins with electrical tape or equivalent.
- 

# TRONITEC

1800 Sandy Plains Pkwy., Suite 120, Marietta, GA 30066

800-962-2588

**[www.tronitec.com](http://www.tronitec.com)**

Tronitec, Inc. repairs, refurbishes and resells equipment made by the original equipment manufacturers. Tronitec, Inc. is not associated with, affiliated with, related to, authorized by, nor certified by referenced companies. Manufacturers names, product names and part numbers are for reference and identification purposes only. All product names and company logos are the trademarks of their respective owners.