

**TRONITEC SERVICE DOCUMENT (TSD# 37)**  
**SERVICE BULLETIN REGARDING WAYNE ANNUNCIATOR BOARD**  
**Models: 883074-R01**

This board **DOES NOT** have a contrast adjustment for the 880590-R01 display. If the display is blank or shows solid black squares, the contrast adjustment must be made using RP1 on the OCPT main board.

Tronitec, Inc. repairs, refurbishes, and resells equipment made by the original equipment manufacturers. Tronitec, Inc. is not associated with, affiliated with, related to, authorized by, nor certified by referenced companies. Manufacturers names, product names and part numbers are for reference and identification purposes only. All product names and company logos are the trademarks of their respective owners.