

Tronitec Service Document # 54

Item Code 6923

Gilbarco Power Supply Replacement

To replace OEM Part # M02870B008S / Q13086-103



- When installing Power Supply Item Code 6923
- There is a 24 pin / 20 pin connector.
- 4 Pins slide off for a 20 pin required connection.

TRONITEC

1800 Sandy Plains Pkwy., Suite 120, Marietta, GA 30066

800-962-2588

www.tronitec.com

Tronitec, Inc. repairs, refurbishes and resells equipment made by the original equipment manufacturers. Tronitec, Inc. is not associated with, affiliated with, related to, authorized by, nor certified by referenced companies. Manufacturers names, product names and part numbers are for reference and identification purposes only. All product names and company logos are the trademarks of their respective owners.